



## State of Utah

# Department of Natural Resources

MICHAEL R. STYLER Executive Director

# Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:				
Company	Dennis Ware Controller			
OGM	Pete Hess Environmental Scientist III			

# **Inspection Report**

Permit Number:	C0070038		
Inspection Type:	PARTIAL		
Inspection Date:	Thursday, November 16, 2006		
Start Date/Time:	11/16/2006 12:45:00 PM		
End Date/Time:	11/16/2006 2:15:00 PM		
Last Inspection:	Wednesday, October 11, 2006		

Inspector: Pete Hess, Environmental Scientist III

Weather: 40's F. Overcast over Castle Gate

InspectionID Report Number: 1139

**Types of Operations** 

Accepted by: whedberg

11/28/2006

Permitee: PLATEAU MINING CORP
Operator: PLATEAU MINING CORP

Site: WILLOW CREEK MINE
Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

#### **Current Acreages**

<b>Total Permitted</b>	14,670.00
<b>Total Disturbed</b>	176.35
Phase I	
Phase II	
Phase III	

#### Mineral Ownership

✓ Federal	✓ Underground
☐ State	Surface
☐ County	✓ Loadout
<b>✓</b> Fee	Processing
<b>✓</b> Other	Reprocessing

### Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee's second quarter 2006 surface water monitoring information was uploaded to the Division web site on September 11, 2006. The Permittee continues to meet the Special Permit Condition included as Attachment "A" of the current State permit.

There are no pending compliance actions for the Willow Creek Mine permit area.

The Mine facilities from the access gate up Canyon to the propane storage tank facility (including the Mine buildings have received Phase III bond release (Task ID #2521) as of May 9, 2006. The buildings are now owned by the College of Eastern Utah, and constitute the Western Energy Training Center.

Phase III bond release has also been granted by the DOGM for the area up-Canyon of the School House Canyon drainage area all the way to the gate on the north side of the water process pond. This now belongs to the Price River Water Improvement District.

The following areas are still inspectable by the DOGM; Crandall Canyon, Gravel Canyon, School House Canyon, the reclaimed rail loadout facility, and the area from the Mine facilities access gate encompassing the long and short tunnels, the Mine site sediment pond, the Castle Gate access road from the Permittee's gate up to the School House drainage mentioned above.

Inspector's Signature:

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Date Friday, November 17, 2006

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Thursday, November 16, 2006

Page 2 of 4

# REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	<b>V</b>		<b>✓</b>	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	<b>✓</b>			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>✓</b>		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	<b>✓</b>			
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives		<b>✓</b>		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		<b>✓</b>	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	<b>✓</b>		<b>✓</b>	
11.	Contemporaneous Reclamation	<b>V</b>		<b>V</b>	
12.	Backfilling And Grading		<b>V</b>		
13.	Revegetation	<b>✓</b>		✓	
14.	Subsidence Control		<b>V</b>		
15.	Cessation of Operations				
16.a Roads: Construction, Maintenance, Surfacing		<b>V</b>		<b>V</b>	
16.b	Roads: Drainage Controls	<b>✓</b>			
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	<b>✓</b>			
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance	<b>✓</b>		<b>✓</b>	
22.	Other				

Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Thursday, November 16, 2006

Page 3 of 4

#### 2. Signs and Markers

The placement of Permittee identification signs in reclaimed areas which remain under R645 jurisdiction was discussed, (particularly the School House Canyon area, and the reclaimed rail loadout facility). The Division recommended that a sign be placed identifying the Permittee in the reclaimed rail car loading area. However, the other areas do not need signs because they are adjacent to an access which is not a public road. This road accesses Price River Water Improvement District facilities (private), Plateau Mining Company reclaimed areas (private), and a utility corridor providing services to both Helper City and Price City. The PacifiCorp Carbon Plant also has a need to be able to use this access.

#### 3. Topsoil

With the exception of one topsoil pile located at the Crandall Canyon gate, all topsoil storage piles have been utilized for reclamation of the site. The Permittee elected not to use the material in this pile due to the large amount of "white top" in the vegetative cover. A "topsoil storage" sign remains on the pile. The Permittee should remove the sign to avoid concern.

#### 4.b Hydrologic Balance: Sediment Ponds and Impoundments

The Mine site pond below the Western Energy Training Center is inspected on a quarterly basis by personnel from EarthFax Engineering, Salt Lake City, Utah. There was no water in the pond this day. The primary riser and secondary open spillway appeared capable of functioning as designed.

#### 4.e Hydrologic Balance: Effluent Limitations

With the exception of pond 001A (Mine site pond), all UPDES outfalls have been removed. The status of the transfer of pond 001A to the Western Energy Training Center as part of the storm water permit is pending.

#### 7. Coal Mine Waste, Refuse Piles, Impoundments

The School House Canyon reclaimed waste rock facility has received Phase I bond release. As observed this day, the area appears stable, and the revegetation cover appears to be doing well. There were no visible signs of erosion in the lower reaches of the re-established drainage.

#### 10. Slides and Other Damage

Mr. Ware informed the DOGM this day that a section of the Castle Gate sandstone escarpment which separates School House Canyon from Barn Canyon had recently collapsed, with most of the material reporting to the surface of the reclaimed waste rock pile. The incident occurred just prior to a bond relaease inspection conducted by Mr. Henry Austin of the Office of Surface Mining of the waste facility.

**Inspection Continuation Sheet** 

Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Thursday, November 16, 2006

Page 4 of 4

#### 11. Contemporaneous Reclamation

Both of the reclaimed/backfilled air shafts in Crandall Canyon have settled. The barrier fences and signs are adequate to warn unauthorized personnel of the danger associated with these reclamation areas. Mr. Ware has made arrangements to have additional material placed where the ground has settled.

# 13. Revegetation

The vegetation in Gravel Canyon appears to be doing very well.

# 16.a Roads: Construction, Maintenance, Surfacing

There are two minor erosion rills across the road accessing the Crandall Canyon facilities. Also, minor sandstone failures have placed debris in the ditches paralleling the cutbank toes. The Permittee has made arrangements to have these issues corrected.

# 21. Bonding and Insurance

The Division has reviewed and approved a reduction in the amount of reclamation bond for the Willow Creek site (from \$4,410,114 to \$2,275,114) effective October 27, 2006.